Resolution No. 210581

TIO Committee Meeting July 21, 2021






General Services Presentation



City Hall Parking Garage (CHPG) Condition Update & Various Repair/Replacement Cost Options

Option One: \$5 Million

Repair/Restore CH Parking Garage and Plaza Waterproofing Extends Life 25+ years






City Hall Parking Garage (CHPG) Condition Update & Various Repair/Replacement Cost Options

Option Two: \$17 Million

Option One with New ADA Access to South Entrance; Replace Porch and Main Stairs





City Hall Parking Garage (CHPG) Condition Update & Various Repair/Replacement Cost Options

Option Three: \$39 Million

New Garage, Plaza and South Entrance Vestibule with ADA Access to South Entrance; Replace Porch and Main Stairs Extends Life 60+ years





Additional Potential City Hall Life Safety Repairs/Improvements

Replace / repair 65 HVAC Air Handlers - \$3.75 Million

Add Fire Suppression 21 Floors - \$10.5 Million

Core Plumbing Piping Replacement - \$3.5 Million

Elevator cabling/infrastructure - \$2.5 Million



Next Steps

- Engage a consultant for municipal building critical repair assessment
- Prioritize repairs in correlation with funding
- Digital database to monitor building conditions in real time



Building Code

International Building Code

Construction Standards

Not a Maintenance Code



Recurring Structural Inspections

Current Requirements

Owner to submit Engineer's Report on Structural Adequacy Every 5 Years

- Occupied Underground Spaces (Caves)
- Radio/Television Towers
- Multi-Level Parking Structures (Beginning 15th year)



Climatic/Environmental Considerations

KANSAS CITY DOES NOT HAVE: High seismic activity Hurricanes Coastal Effects – Salt air, wave action

KANSAS CITY DOES HAVE: Tornados Multiple Freeze/Thaw Cycles



Building Types

Highrise Concrete Frame Steel Frame Heavy Timber Masonry (w Heavy Timber/Wood Frame) Wood Frame



Potential Expansion in Recurring/Periodic Inspections

- Un-reinforced masonry Structures
- Privately Owned Pedestrian Bridges over Public Ways.
- Retaining walls over a certain height?
- Exterior stairs on buildings over a certain number of stories.
- Balconies on buildings over a certain height or certain size.



Stakeholder Panel Recommendation

Stakeholder group including:

- Building Owners
- Structural Engineers
- Architects

Tasks:

- Review Current KCMO Requirements for Existing Buildings
- Examples from other Cities
- Potential Changes Applicable to both Publicly and Privately Owned Structures

Identify Time and Cost Factors associated with revised standards.



Questions / Comments / Thank You



